


Valley View Ranch



PRELIMINARY - NOT TO BE RECORDED FOR ANY PURPOSE

CURVE TABLE

CURVE	LENGTH	RADIUS	CHORD BEARING	CHORD
C1	183.62'	1786.78'	S 20°08'30" E	183.62'
C2	88.04'	100.00'	S 1°31'30" W	88.04'
C3	188.84'	708.08'	S 52°58'30" W	188.84'

LINE TABLE

LINE	BEARING	LENGTH
L3	N 17°18'30" W	32.00'
L4	S 32°51'18" W	33.77'
L5	N 47°11'53" E	80.53'
L6	S 34°21'53" W	80.50'
L7	N 07°08'28" E	103.05'
L8	N 55°59'53" E	80.04'
L9	S 30°18'30" E	80.64'
L10	S 20°41'53" E	104.47'
L11	N 28°15'27" W	45.53'
L12	N 30°10'52" W	80.88'
L13	S 02°11'00" E	249.77'
L14	S 02°11'00" E	415.33'
L15	S 02°11'00" E	415.33'
L16	N 02°11'00" E	181.31'
L17	N 02°08'10" W	80.88'
L18	N 02°08'10" W	75.81'

Carl Leyendecker
Survey No. 663
Abstract No. 1119

P. Baumann
Survey No. 510
Abstract No. 1059

P. Baumann
Survey No. 511
Abstract No. 1063